

FIG. 1




FIG. 3
SECTION

Q.P = Q-PROX SENSOR
S.B = SEALED BULK HEAD
B = BOOT




FIG. 2